



Stanchions




FWALKACS

Description: Cored Through




FWALKACDOSO

Description: Drilled One Side




FWALKASOS

Description: Side Offset




FWALKASC

Description: Side Conveyor



FWALKAPS

Description: Platform




FWALKAPC

Description: Platform Corner



FWALKASS

Description: Side 38.1 Mid



FWALKAWS

Description: Welded

FWALKAPDOSO

Description: Drilled One Side

FWALKASSDLSO & FWALKASSDRSO

Description: Drilled One Side

FWALKAWS

Description: Drilled One Side

OAD = Overall Dimensions

Please contact your local branch for more enquires and stock levels.

Note that some products may not be available in all states, and variations or substitutions may be an option.

Diagrams are schematic only and not intended as specification drawings.